

Produtos e modelos habilitados à fruição dos benefícios fiscais da Lei de Informática

Nome Fantasia:	HEWLETT-PACKARD
Razão Social:	HEWLETT-PACKARD BRASIL LTDA
CNPJ:	61.797.924/0029-56
Endereço:	Rodovia SP 340, nº s/n, KM 118,5 Bloco C Sala 2 Barao Geraldo Campinas / SP - 13024500
Contato:	Ricardo Brognoli ricardo.brognoli@hpe.com (11)45728231 https://www.hpe.com/br/pt/home.html

Produto:	Impressora a jato de tinta líquida, com velocidade de impressão inferior a 30 páginas por minuto e com largura de impressão inferior ou igual a 420mm
Processo MCT/Data:	01250.004222/2017-79 de 23/01/2017
CNPJ da Incentivada:	61797924002956
Portaria MCT/MDIC/MF:	2847, de 23/05/2017 DOU 24/05/2017 - Produto Transferido da Portaria: 589, de 18/08/2003 DOU 20/08/2003 (http://pesquisa.in.gov.br/imprensa/jsp/visualiza/index.jsp?jornal=1&pagina=9&data=24/05/2017)
Modelos:	C6427A (# 696 e AC8) - HP Deskjet DJ930C; C6431A-B (# 696 e AC8) - HP Deskjet DJ940C; C6428A (# 696 e AC8) - HP Deskjet DJ950C; C6414A (# 696 e AC8) - HP Deskjet DJ840C; C6464A (# 696 e AC8) - HP Deskjet DJ640C; C6737A (# 696 e AC8) - HP Officejet G55; C6737A (# 696 e AC8) - HP Officejet G85; C6740A (# 696 e AC8) - HP Officejet G95; C6430A-B (# 696 e AC8) - HP Deskjet DJ920C; C8942A (# 696 e #AC8) - HP Deskjet DJ656C; C8426A (# 696 e #AC8) - HP PSC 750 (Multifuncional); C8436A (# 696 e #AC8) - HP PSC 950 (Multifuncional); C8946A (# 696 e #AC8) - (Impressora); C8947A (# 696 e #AC8) - (Impressora); C6487A (# 696 e #AC8) - (Impressora); C8952A (# 696 e #AC8) ? (Impressora); C6736A# AC8 HP Officejet G55; C6736A#696 HP Officejet G55; C6431A#AC8 HP Deskjet DJ940C; C6431A#696 HP Deskjet DJ940C; C6430A#AC8 HP Deskjet DJ920C; C6430A#696 HP Deskjet DJ920C; C6430A#ABM HP Deskjet DJ920C; C6431A-006 HP Deskjet DJ940C; C6431A#ABM HP Deskjet DJ940C; C6430A-006 HP Deskjet DJ920C; C6427A-001 HP Deskjet DJ930C; C6428A-001 HP Deskjet DJ950C; C8946C#696 Deskjet 3320; C8946#AC8 Deskjet 3320; C8958A#696 Deskjet 3425; C8958A#AK4 Deskjet 3425; C8958A#AC8 Deskjet 3425; DJ 5650 C6490A #AK4; DJ 5650 C6490A #AC8; DJ 5650 C6490A #AKV; DJ 5150 C8962A #AK4; DJ 5150 C8962A #AC8; DJ 5150 C8962A #AKV; DJ 3650 C8974A #AK4; DJ 3650 C8974A #AC8; DJ 3650 C8974A #AKV; DJ 3550 C8991A #AK4; DJ 3550 C8991A #AC8; DJ 3550 C8991A #AKV; DJ 3535 C8995A #AK4; DJ 3535 C8995A #AC8; DJ 3535 C8995A #AKV;PSC 1210 Q1662A #AK4; PSC 1210 Q1662A #AC8; PSC 1210 Q1662A #AKV; PSC 1110 Q1652A #AK4; PSC 1110 Q1652A #AC8; PSC 1110 Q1652A #AKV; PSC 1350 Q3501A #AK4; PSC 1350 Q3501A #AC8; PSC 1350 Q3501A #AKV.

Produto:	Impressora a laser, monocromática, com velocidade de impressão inferior a 30 páginas por minuto e com largura de impressão inferior ou igual a 420mm
Processo MCT/Data:	01250.004222/2017-79 de 23/01/2017
CNPJ da Incentivada:	61797924002956
Portaria MCT/MDIC/MF:	2847, de 23/05/2017 DOU 24/05/2017 - Produto Transferido da Portaria: 589, de 18/08/2003 DOU 20/08/2003 (http://pesquisa.in.gov.br/imprensa/jsp/visualiza/index.jsp?jornal=1&pagina=9&data=24/05/2017)
Modelos:	LJ1200 C7044A; LJ1200 C7048A; LJ1200 C7045A; LJ2200 C7058A; LJ2200 C7063A; LJ2200 C7061A; LJ4100 C8049A; LJ4100 C8050A; LJ4100 C8051A; LJ4100 C8052A; C7064A; Q2425A; Q2426A; Q2427A; Q2428A; LJ 1300 Q1334A; LJ 1300 Q1335A; LJ 2300 Q2472A; LJ 2300 Q2473A; LJ 2300 Q2474A; LJ 2300 Q2475A; LJ 2300 Q2477A.

Produto:	Impressora a laser, monocromática, com velocidade de impressão superior ou igual a 30 páginas por minuto
Processo MCT/Data:	01250.004222/2017-79 de 23/01/2017
CNPJ da Incentivada:	61797924002956
Portaria MCT/MDIC/MF:	2847, de 23/05/2017 DOU 24/05/2017 - Produto Transferido da Portaria: 589, de 18/08/2003 DOU 20/08/2003 (http://pesquisa.in.gov.br/imprensa/jsp/visualiza/index.jsp?jornal=1&pagina=9&data=24/05/2017)
Modelos:	LJ4200 Q2425A; LJ4200 Q2426A; LJ4200 Q2427A; LJ4200 Q2428A

Produto:	Unidade de processamento digital de grande capacidade, baseada em microprocessadores
Processo MCT/Data:	01250.004222/2017-79 de 23/01/2017
CNPJ da Incentivada:	61797924002956
Portaria MCT/MDIC/MF:	2847, de 23/05/2017 DOU 24/05/2017 - Produto Transferido da Portaria: 762, de 13/12/2001 DOU 14/12/2001 (http://pesquisa.in.gov.br/imprensa/jsp/visualiza/index.jsp?jornal=1&pagina=9&data=24/05/2017)
Modelos:	L3000; HP RP7400; HP 9000 RP5400; HP 9000 RP5405; HP 9000 RP5430; HP 9000 RP5470; HP 9000 RP5030; HP 9000 RP7400; HP 9000 RP7405; HP 9000 RP7410; HP 9000 RP8400; HP 9000 RP8405; INTEGRITY RX4600; INTEGRITY RX4605; INTEGRITY RX4610; INTEGRITY RX4620; INTEGRITY RX4620; INTEGRITY RX4630; INTEGRITY RX4640; INTEGRITY RX4650; INTEGRITY RX4660; INTEGRITY RX4670; INTEGRITY RX4680; INTEGRITY RX4690; INTEGRITY RX5600; INTEGRITY RX5605; INTEGRITY RX5610; INTEGRITY RX5620; INTEGRITY RX5630; INTEGRITY RX5640; INTEGRITY RX5650; INTEGRITY RX5660; INTEGRITY RX5670; INTEGRITY RX5680; INTEGRITY RX5690; INTEGRITY RX6600; INTEGRITY RX6605; INTEGRITY RX6610; INTEGRITY RX6620; INTEGRITY RX6630; INTEGRITY RX6640; INTEGRITY RX6650; INTEGRITY RX6660; INTEGRITY RX6670; INTEGRITY RX6680; INTEGRITY RX6690; INTEGRITY RX7600; INTEGRITY RX7605; INTEGRITY RX7610; INTEGRITY RX7620; INTEGRITY RX7630; INTEGRITY RX7640; INTEGRITY RX7650; INTEGRITY RX7660; INTEGRITY RX7670; INTEGRITY RX7680; INTEGRITY RX7690; INTEGRITY RX8600; INTEGRITY RX8605; INTEGRITY RX8610; INTEGRITY RX8620; INTEGRITY RX8630; INTEGRITY RX8640; INTEGRITY RX8650; INTEGRITY RX8660; INTEGRITY RX8670; INTEGRITY RX8680; INTEGRITY RX8690; INTEGRITY RX9600; INTEGRITY RX9605; INTEGRITY RX9610; INTEGRITY RX9620; INTEGRITY RX9630; INTEGRITY RX9640; INTEGRITY RX9650; INTEGRITY RX9660; INTEGRITY RX9670; INTEGRITY RX9680; INTEGRITY RX9690; PROLIANT DL720; PROLIANT DL740; PROLIANT DL760; PROLIANT DL780; PROLIANT ML710; PROLIANT ML730; PROLIANT ML750; PROLIANT ML770; PROLIANT ML790; HP 9000 RP4400; HP 9000 RP4405; HP 9000 RP4410; HP 9000 RP4420; HP 9000 RP4430; HP 9000 RP4440; HP 9000 RP4450; HP 9000 RP4460; HP 9000 RP4470; HP 9000 RP4480; HP 9000 RP4490; HP 9000 RP5410; HP 9000 RP5420; HP 9000 RP5440; HP 9000 RP5450; HP 9000 RP5460; HP 9000 RP5480; HP 9000 RP5490; HP 9000 RP6400; HP 9000 RP6405; HP 9000 RP6410; HP 9000 RP6420; HP 9000 RP6430; HP 9000 RP6440; HP 9000 RP6450; HP 9000 RP6460; HP 9000 RP6470; HP 9000 RP6480; HP 9000 RP6490; HP 9000 RP7420; HP 9000 RP7430; HP 9000 RP7440; HP 9000 RP7450; HP 9000 RP7460; HP 9000 RP7470; HP 9000 RP7480; HP 9000 RP7490; HP 9000 RP8410; HP 9000 RP8420; HP 9000 RP8430; HP 9000 RP8440; HP 9000 RP8450; HP 9000 RP8460; HP 9000 RP8470; HP 9000 RP8480; HP 9000 RP8490; HP 9000 RP9400; HP 9000 RP9405; HP 9000 RP9410; HP 9000 RP9420; HP 9000 RP9430; HP 9000 RP9440; HP 9000 RP9450; HP 9000 RP9460; HP 9000 RP9470; HP 9000 RP9480; HP 9000 RP9490; PROLIANT DL745; PROLIANT DL765.(14-05-10: DL785)(14-05-10: BL870C)(14-05-10: BL890C)(10-11-10: DL980)(02-09-11: DL580)(02-09-11: BL680C)(21-10-13: GRD DL560)(11-12-17: GRD SIMPLIVITY 380)(21-03-18: (GRD) DL360)(21-03-18: (GRD) DL380)(23-03-18: GRD DL560)(23-03-18: GRD DL580)(23-03-18: GRD BL460C)(23-03-18: GRD BL660C)(23-03-18: GRD CS500)(23-03-18: (GRD) BL890C)(23-03-18: (GRD) BL870C)(23-03-18: (GRD) BL860C)

Produto:	Unidade de processamento digital de média capacidade, baseada em microprocessadores
Processo MCT/Data:	01250.004222/2017-79 de 23/01/2017
CNPJ da Incentivada:	61797924002956
Portaria MCT/MDIC/MF:	2847, de 23/05/2017 DOU 24/05/2017 - Produto Transferido da Portaria: 762, de 13/12/2001 DOU 14/12/2001 (http://pesquisa.in.gov.br/imprensa/jsp/visualiza/index.jsp?jornal=1&pagina=9&data=24/05/2017)
Modelos:	L1000; L2000; PROLIANT; ALPHA SERVER; DL520; DL540; DL560; DL580; ML510; ML530; ML550; ML570; ML590; DL720; DL740; DL760; DL780; ML710; ML730; ML750; ML770; ML790; BL20P; BL40P; HP RP5400; HP RP5405; HP RP5470; HP RP5430; HP 9000 RP5400; HP 9000 RP5405; HP 9000 RP5430; HP 9000 RP5470; HP 9000 RP5030; INTEGRITY RX3600; INTEGRITY RX3605; INTEGRITY RX3610; INTEGRITY RX3620; INTEGRITY RX3630; INTEGRITY RX3640; INTEGRITY RX3650; INTEGRITY RX3660; INTEGRITY RX3670; INTEGRITY RX3680; INTEGRITY RX3690; INTEGRITY RX4600; INTEGRITY RX4605; INTEGRITY RX4610; INTEGRITY RX4620; INTEGRITY RX4620; INTEGRITY RX4630; INTEGRITY RX4640; INTEGRITY RX4650; INTEGRITY RX4660; INTEGRITY RX4670; INTEGRITY RX4680; INTEGRITY RX4690; INTEGRITY RX5600; INTEGRITY RX5605; INTEGRITY RX5610; INTEGRITY RX5620; INTEGRITY RX5630; INTEGRITY RX5640; INTEGRITY RX5650; INTEGRITY RX5660; INTEGRITY RX5670; INTEGRITY RX5680; INTEGRITY RX5690; INTEGRITY RX6600; INTEGRITY RX6605; INTEGRITY RX6610; INTEGRITY RX6620; INTEGRITY RX6630; INTEGRITY RX6640; INTEGRITY RX6650; INTEGRITY RX6660; INTEGRITY RX6670; INTEGRITY RX6680; INTEGRITY RX6690; INTEGRITY RX7600; INTEGRITY RX7605; INTEGRITY RX7610; INTEGRITY RX7620; INTEGRITY RX7630; INTEGRITY RX7640; INTEGRITY RX7650; INTEGRITY RX7660; INTEGRITY RX7670; INTEGRITY RX7680; INTEGRITY RX7690; HP 9000 RP3400; HP 9000 RP3405; HP 9000 RP3410; HP 9000 RP3420; HP 9000 RP3430; HP 9000 RP3440; HP 9000 RP3450; HP 9000 RP3460; HP 9000 RP3470; HP 9000 RP3480; HP 9000 RP3490; HP 9000 RP4400; HP 9000 RP4405; HP 9000 RP4410; HP 9000 RP4420; HP 9000 RP4430; HP 9000 RP4440; HP 9000 RP4450; HP 9000 RP4460; HP 9000 RP4470; HP 9000 RP4480; HP 9000 RP4490; HP 9000 RP5410; HP 9000 RP5420; HP 9000 RP5440; HP 9000 RP5450; HP 9000 RP5460; HP 9000 RP5480; HP 9000 RP5490; HP 9000 RP6400; HP 9000 RP6405; HP 9000 RP6410; HP 9000 RP6420; HP 9000 RP6430; HP 9000 RP6440; HP 9000 RP6450; HP 9000 RP6460; HP 9000 RP6470; HP 9000 RP6480; HP 9000 RP6490; HP 9000 RP7420; HP 9000 RP7430; HP 9000 RP7440; HP 9000 RP7450; HP 9000 RP7460; HP 9000 RP7470; HP 9000 RP7480; HP 9000 RP7490; PROLIANT DL565; PROLIANT DL585; PROLIANT ML575; PROLIANT DL745; PROLIANT DL765; PROLIANT BL25P; PROLIANT BL35P; PROLIANT BL45P; PROLIANT DL160; PROLIANT DL 165; PROLIANT DL 180; PROLIANT XW460; INTEGRITY BL860; PROLIANT DL185; PROLIANT BL325; PROLIANT BL460; PROLIANT BL465; PROLIANT BL480; PROLIANT BL485; PROLIANT BL680; PROLIANT BL685 E PROLIANT XW25P. (03-02-09: HP BLADESYSTEM C7000 ENCLOSURE - PROLIANT BL460C)(14-05-10: BL890C)(14-05-10: DL785)(14-05-10: BL870C)(14-05-10: BL860C)(10-11-10: DL980) (02-09-11: DL380) (02-09-11: DL360) (02-09-11: ML350) (09-02-12: MED DL380P) (09-02-12: MED DL360P) (09-02-12: MED ML350P) (20-07-12: MED DL380E) (20-07-12: MED DL385P) (20-07-12: MED ML350E) (23-11-12: ML310EGEN8) (23-11-12: DL320EGEN8) (23-11-12: STOREVIRTUAL 4330) (23-11-12: STOREEASY 1430) (28-01-13: BL660C) (28-01-13: MED SL230S) (28-01-13: MED SL230S) (28-01-13: MED SL230S) (05-02-13: MED SL250S) (26-08-13: MED DL560)(12-08-14: (MED) 4335) (12-08-14: MED - FILE CNTL (FILE CONTROLLER)(03-01-17: MED HC380) (17-11-17: MED SIMPLIVITY 380) (15-12-17: MED SY480) (15-12-17: MED SY660) (21-03-18: (MED) DL180) (21-03-18: MED ML350) (21-03-18: (MED) DL360) (21-03-18: (MED) DL380) (21-03-18: MED ML150) (23-03-18: MED DL560) (23-03-18: MED DL580) (23-03-18: MED BL460C) (23-03-18: MED BL660C) (23-03-18: MED HC380) (23-03-18: MED CS500) (23-03-18: (MED) BL870C) (23-03-18: (MED) BL860C) (23-03-18: (MED) BL890C) (06-04-18: MED DL160)
Produto:	Unidade de processamento digital de muito grande capacidade
Processo MCT/Data:	01250.004222/2017-79 de 23/01/2017
CNPJ da Incentivada:	61797924002956
Portaria MCT/MDIC/MF:	2847, de 23/05/2017 DOU 24/05/2017 - Produto Transferido da Portaria: 762, de 13/12/2001 DOU 14/12/2001 (http://pesquisa.in.gov.br/imprensa/jsp/visualiza/index.jsp?jornal=1&pagina=9&data=24/05/2017)
Modelos:	N4000; A3639C; HP RP7410; HP 9000 RP7400; HP 9000 RP7405; HP 9000 RP7410; HP 9000 RP8400; HP 9000 RP8405; INTEGRITY RX7600; INTEGRITY RX7605; INTEGRITY RX7610; INTEGRITY RX7620; INTEGRITY RX7630; INTEGRITY RX7640; INTEGRITY RX7650; INTEGRITY RX7660; INTEGRITY RX7670; INTEGRITY RX7680; INTEGRITY RX7690; INTEGRITY RX8600; INTEGRITY RX8605; INTEGRITY RX8610; INTEGRITY RX8620; INTEGRITY RX8630; INTEGRITY RX8640; INTEGRITY RX8650; INTEGRITY RX8660; INTEGRITY RX8670; INTEGRITY RX8680; INTEGRITY RX8690; INTEGRITY RX9600; INTEGRITY RX9605; INTEGRITY RX9610; INTEGRITY RX9620; INTEGRITY RX9630; INTEGRITY RX9640; INTEGRITY RX9650; INTEGRITY RX9660; INTEGRITY RX9670; INTEGRITY RX9680; INTEGRITY RX9690; HP 9000 RP7420; HP 9000 RP7430; HP 9000 RP7440; HP 9000 RP7450; HP 9000 RP7460; HP 9000 RP7470; HP 9000 RP7480; HP 9000 RP7490; HP 9000 RP8410; HP 9000 RP8420; HP 9000 RP8430; HP 9000 RP8440; HP 9000 RP8450; HP 9000 RP8460; HP 9000 RP8470; HP 9000 RP8480; HP 9000 RP8490; HP 9000 RP9400; HP 9000 RP9405; HP 9000 RP9410; HP 9000 RP9420; HP 9000 RP9430; HP 9000 RP9440; HP 9000 RP9450; HP 9000 RP9460; HP 9000 RP9470; HP 9000 RP9480; HP 9000 RP9490.(14-05-10: BL870C)(14-05-10: BL890C)(10-11-10: DL980)

Produto:	Unidade de processamento digital, de pequena capacidade, baseada em microprocessador
Processo MCT/Data:	01250.004222/2017-79 de 23/01/2017
CNPJ da Incentivada:	61797924002956
Portaria MCT/MDIC/MF:	2847, de 23/05/2017 DOU 24/05/2017 - Produto Transferido da Portaria: 589, de 18/08/2003 DOU 20/08/2003 (http://pesquisa.in.gov.br/imprensa/jsp/visualiza/index.jsp?jornal=1&pagina=9&data=24/05/2017)
Modelos:	P4072A; P4075A; P5052A; P5124A; P5072A; P4744A; P5055A; P5056A; P5057A; P5121A; P5132A; P5058A; P5059A; P5580A; P5582A; P5583A; P5584A; P3376C; P4279C; P4955C; P3379C; P4946C; P4954C; P3378C; P4936C; P4947C; P3377C; P4953C; P1719C; P3254B; P3256B; P3261B; P4177B; P4197B; P4864B; P4867B; P4198B; P4200B; P4865B; P4178C; P4199C; P4200C; P4844C; P4866C; P4867C; P4768A; P6096A; P6100A; P6101A; P5769A; P5770A; P5771A; P5772A; P5773A; P3488A; P3489A; P4594A; P4595A; P2588A; P5371A; P1802A; P2478A; P2478B; P1812A; P2465A; P4632A; P4634A; P1827A; P1830A; P4636A; P4638A; P4648A; P4649A; P4652A; P4653A; P4654A; P4655A; P3497A; P3498A; P3499A; P3501A; P3502A; P3503A; P3505A; P3506A; P3507A; P3537A; P6179AV; P7941B; P7942B; P7943B; P7944B; P7945B; P7946B; P7947B; P7948B; P7949B; P6159W; P6161W; P6162W; P5054W; P5072A; P5124A; P5574W; P4768A; P4768B; P6096B; P6100B; P6101B; P6105W; P6106W; P7854B; P7855B; P7856B; P7857B; P7858B; P7870B; P7871B; P7872B; P7873B; P7934B; P7935B; P7936B; P7937B; P7938B; P7939B; P3765W; P5659AV; P5660AV; P5661AV; P5747W; P5748W; P5749W; P5751W; P5752W; P5753W; P5761B; P5769B; P5770B; P5771B; P6185W; P6187W; P6188B; P6196W; P6197W; P6198W; P6212B; P7859B; P7860B; P7861B; P7862B; P7864B; P7865B; P7866B; P7868B; P8100AV; P8101AV; P7879B; P7880B; P8758AV; P7919B; P7920B; P7921B; P7923B; P4281AV; P4957W; P5803W; P5802C; P5801C; P4321C; P7941B; P7942B; P7943B; P7944B; P6106W; P7857B; P6105W; P6101B; P7856B; P6100B; P7858B; P7855B; P7854B; P4390AV; P5660AV; P6198W; P6197W; P5770B; P5769B; P6188B; P5761B; P6196W; P5747W; P5748W; P6185W; P5752W; P5749W; P5751W; P3763W; P5773B; P3764W; P3765W; P6187W; P6192W; P6193W; P6194W; P6195W; P6189W; P5753W; P3766W; P6190W; P7864B; P7859B; P7862B; P7861B; P7860B; P7863B; P5404A; P5403A; P2588A; P2589A; P2592AV; P2587A; P4633AV; P4635AV; P4637AV; P4639AV; HP VECTRA VL400; HP VECTRA VL420; HP E-PC 42 ; HP VECTRA XE-320; DESKPRO; IPAQ; PRESÁRIO; EVO; PROLIANT DL120; PROLIANT DL140; PROLIANT DL160; PROLIANT DL180; PROLIANT ML110; PROLIANT ML130; PROLIANT ML150; PROLIANT ML170; PROLIANT ML190; PROLIANT; HP SERVER; PROLIANT DL320; PROLIANT DL340; PROLIANT DL360; PROLIANT DL380; PROLIANT DL520; PROLIANT DL540; PROLIANT DL560; PROLIANT DL580; PROLIANT ML310; PROLIANT ML330; PROLIANT ML350; PROLIANT ML370; PROLIANT ML390; PROLIANT ML510; PROLIANT ML530; PROLIANT ML550; PROLIANT ML570; PROLIANT ML590; PROLIANT BL10E; PROLIANT BL20P; PROLIANT BL40P; HP SERVER TC2120; HP SERVER TC2130; HP SERVER TC2140; HP SERVER TC2150; INTEGRITY RX2600; INTEGRITY RX2605; INTEGRITY RX2610; INTEGRITY RX2620; INTEGRITY RX2630; INTEGRITY RX2640; INTEGRITY RX2650; INTEGRITY RX2660; INTEGRITY RX2670; INTEGRITY RX2680; INTEGRITY RX2690; INTEGRITY RX3600; INTEGRITY RX3605; INTEGRITY RX3610; INTEGRITY RX3620; INTEGRITY RX3630; INTEGRITY RX3640; INTEGRITY RX3650; INTEGRITY RX3660; INTEGRITY RX3670; INTEGRITY RX3680; INTEGRITY RX3690; HP BUSINESS DESKTOP D325; HP COMPAQ BUSINESSDESKTOP D330; HP COMPAQ BUSINESSDESKTOP D530; EVO D300; EVO D300V; EVO D301; EVO D301V; EVO D310; EVO D310V; EVO D311V; EVO D320; EVO D325; EVO D330; EVO D500; EVO D500I; EVO D510; EVO D510 EPC; EVO D700; HP PROLIANT SERVER ML330; HP PROLIANT SERVER ML350; HP PROLIANT SERVER ML370; HP PROLIANT SERVER ML530; HP PROLIANT SERVER ML570; HP PROLIANT SERVER DL360; HP PROLIANT SERVER DL380; HP PROLIANT SERVER DL560; HP PROLIANT SERVER DL580; HP PROLIANT SERVER DL740; HP PROLIANT SERVER DL760; HP COMPAQ BUSINESS DESKTOP DC5000; HP COMPAQ BUSINESS DESKTOP DC7100; PROLIANT DL145; PROLIANT DL365; PROLIANT DL385; PROLIANT DL565; PROLIANT DL585; PROLIANT ML115; PROLIANT ML 155; PROLIANT ML335; PROLIANT ML355; PROLIANT ML375; PROLIANT ML575; PROLIANT BL15E; PROLIANT BL25P; PROLIANT BL35P; PROLIANT BL45P; HP COMPAQ BUSINESS DESKTOP DC5100; PROLIANT DL165; PROLIANT XW460; INTEGRITY BL860; PROLIANT DL125; PROLIANT DL185; PROLIANT BL325; PROLIANT ML125; PROLIANT BL460; PROLIANT BL465; PROLIANT BL480; PROLIANT BL485; PROLIANT BL680; PROLIANT BL685; PROLIANT XW25P.(03-02-09: HP PROLIANT BL260C)(03-02-09: HP BLADESYSTEM C7000 ENCLOSURE - PROLIANT BL460C)(31-01-12: ML350P) (31-01-12: DL360P) (09-02-12: PEQ DL380P) (20-07-12: PEQ DL385P) (20-07-12: PEQ DL380E) (20-07-12: PEQ ML350E) (20-07-12: PEQ DL360E) (06-08-12: ML310E) (06-08-12: DL320E) (28-01-13: PEQ SL230S) (28-01-13: PEQ SL230S) (28-01-13: PEQ SL230S) (05-02-13: PEQ SL250S) (20-03-13: STOREEASY 1430 (PEQ)) (30-04-13: STOREVIRTUAL 4330 (PEQ)) (14-06-13: STOREVIRTUAL 4530 (PEQ))(14-06-13: STOREVIRTUAL 4730 (PEQ))(23-09-13: QR516B SERVICE PROCESSOR (PEQ)) (12-08-14: (PEQ) 4335) (12-08-14: PEQ - FILE CNTL (FILE CONTROLLER))(15-09-14: PEQ DL160) (12-11-14: PEQ ML 150) (22-10-15: PEQ DL20)(25-07-16: PEQ ML30) (15-12-17: PEQ SY480) (15-12-17: PEQ SY660) (15-12-17: PEQ SY660) (15-12-17: PEQ SY660) (08-03-18: PEQ ML30) (21-03-18: (PEQ) DL180) (21-03-18: PEQ ML350) (21-03-18: PEQ ML150) (21-03-18: (PEQ) DL360) (21-03-18: (PEQ) DL380) (23-03-18: PEQ DL560) (23-03-18: PEQ DL20) (23-03-18: PEQ DL580) (23-03-18: PEQ BL460C) (23-03-18: PEQ BL660C) (23-03-18: PEQ CS500) (23-03-18: (PEQ) BL890C) (23-03-18: (PEQ) BL870C) (23-03-18: (PEQ) BL860C) (06-04-18: PEQ DL160)

Voltar